

## PERRY JOHNSON LABORATORY ACCREDITATION, INC.

## Certificate of Accreditation

Perry Johnson Laboratory Accreditation, Inc. has assessed the Laboratory of:

Hammond Company 755 Larry Court, Waukesha, WI 53186

(Hereinafter called the Organization) and hereby declares that Organization is accredited in accordance with the recognized International Standard:

## ISO/IEC 17025:2005

This accreditation demonstrates technical competence for a defined scope and the operation of a laboratory quality management system (as outlined by the joint ISO-ILAC-IAF Communiqué dated January 2009):

Calibration of Optical Comparators and Vision Systems (As detailed in the supplement)

Accreditation claims for such testing and/or calibration services shall only be made from addresses referenced within this certificate. This Accreditation is granted subject to the system rules governing the Accreditation referred to above, and the Organization hereby covenants with the Accreditation body's duty to observe and comply with the said rules.

For PJLA:

Tracy Szerszen President/Operations Manager

Perry Johnson Laboratory Accreditation, Inc. (PJLA) 755 W. Big Beaver, Suite 1325 Troy, Michigan 48084

Initial Accreditation Date:	Issue Date:	Expiration Date:
November 20, 2003	January 11, 2018	January 31, 2020
Accreditation	No.: Ce	rtificate No.:
59250		L18-18

The validity of this certificate is maintained through ongoing assessments based on a continuous accreditation cycle. The validity of this certificate should be confirmed through the PJLA website: <u>www.pjlabs.com</u>



Dimonsional

Certificate of Accreditation: Supplement

Hammond Company

755 Larry Court, Waukesha, WI 53186 Contact Name: John Davenport Phone: 262-798-4243

Accreditation is granted to the facility to perform the following calibrations:

Dimensional				
MEASURED INSTRUMENT, QUANTITY OR GAUGE	RANGE (AND SPECIFICATION WHERE APPROPRIATE)	CALIBRATION AND MEASUREMENT CAPABILITY EXPRESSED AS AN UNCERTAINTY (±)	CALIBRATION EQUIPMENT AND REFERENCE STANDARDS USED	
Optical Comparator – Linear Accuracy <sup>F</sup>	0.01 in to12 in	370 µin	Glass Reticle	
	12 in to 24 in	440 µin		
Optical Comparator- Squareness <sup>F</sup>	Horizontal Displacement at 3 in of Y travel	51 µin		
Optical Comparator – Magnification Accuracy <sup>F</sup>	10 X	0.061 %		
	20 X	0.043 %		
	31.25 X	0.039 %		
	50 X	0.034 %		
	62.5 X	0.022 %		
	100 X	0.017 %		
Vision System – Non-Linear Accuracy <sup>F</sup>	6 in x 8 in	95 µin	Glass Grid	
	6 in x 10 in	110 µin		
	6 in x 12 in	120 µin		
	8 in x 8 in	100 µin		
	12 in x 12 in	120 µin		
	18 in x 18 in	180 µin		
	18 in x 20 in	190 µin		
	18 in x 24 in	220 µin		
Vision System - Z axis <sup>F</sup>	1 in to 4 in	71 µin	Z Step Gage	

- 1. The CMC (Calibration and Measurement Capability) stated for calibrations included on this scope of accreditation represents the smallest measurement uncertainty attainable by the laboratory when performing a more or less routine calibration of a nearly ideal device under nearly ideal conditions. It is typically expressed at a confidence level of 95 % using a coverage factor k (usually equal to 2). The actual measurement uncertainty associated with a specific calibration performed by the laboratory will typically be larger than the CMC for the same calibration since capability and performance of the device being calibrated and the conditions related to the calibration may reasonably be expected to deviate from ideal to some degree.
- 2. The laboratories range of calibration capability for all disciplines for which they are accredited is the interval from the smallest calibrated standard to the largest calibrated standard used in performing the calibration. The low end of this range must be an attainable value for which the laboratory has or has access to the standard referenced. Verification of an indicated value of zero in the absence of a standard is common practice in the procedure for many calibrations but by its definition it does not constitute calibration of zero capacity.
- 3. The presence of a superscript F means that the laboratory performs calibration of the indicated parameter at its fixed location. Example: Outside Micrometer <sup>F</sup> would mean that the laboratory performs this calibration at its fixed location.

This supplement is in conjunction with certificate #L18-18